



Metal adjustment screw Part No.24520085



Application
17.3, d2-33.2, D-36.0, h1-5, H-17, M36*1 FORD Explorer 2010-; FORD Flex/Taurus; LINCOLN MKT/MKS 2009-

FITS THE FOLLOWING

Rack part number	Crossreferences	Application
ATGE40431RB	<p>FORD</p> <p>BB5Z3504DE, DB533D080BB, BB533504GB, BB5Z3504NE, DB5Z3504D, BB533504CB, BB5Z3504H, DB533D080BD, BB5Z3504D, BB5Z3504SE, BB533504GA, BB5Z3504LE, DB533D080BF, BB5Z3504GE, DB533D080BC, BB5Z3504CE, BB5Z3504RE, DB5Z3504DE, BB533504DA, BB5Z3504JE, DB533D080BE</p> <p>INA</p> <p>A00229, A0022905, F565922, H095231142, F56592202, H0952311421, 452001957, 16H0403, F565922, F565922020061, F565922020061CC</p>	Ford Explorer V (2010-2015)
ATGE41151RB	<p>FORD</p> <p>BB5Z3504BE, BB533504FA, BB533504BA, BB5Z3504FE, BB5Z3504AE, BB533504EA,</p>	Ford Explorer V (2010-2015)



	<p>BB5Z3504HE, BB5Z3504EE, BB533504FB, BB533504CA, BB5Z3504G</p> <p>INA</p> <p>A00229, A0022905, F565922, H095231142, F56592202, H0952311421, 452001957, 16H0403, F565922, F565922020061, F565922020061CC</p>	
ATGE41161RB	<p>FORD</p> <p>DB5Z3504BE, EB5Z3504J, DB5Z3504LE, EB5Z3504E, DB5Z3504D, EB5Z3504ME, EB5Z3504B</p> <p>INA</p> <p>A00229, A0022905, F565922, H095231142, F56592202, H0952311421, 452001957, 16H0403, F565922, F565922020061, F565922020061CC</p>	Ford Explorer V (2010-2015)
ATGE43621RB	<p>FORD</p> <p>DB533D080AF, DB5Z3504E, EB5Z3504G, DB5Z3504AE, DB5Z3504NE, DB533D08AC, DB5Z3504FE, EB5Z3504LE, DB5Z3504CE, EB5Z3504D, DB533D08AE, DB5Z3504KE, DB533D08AB, DB5Z3504F, EB5Z3504H, DB5Z3504C, EB5Z3504A, DB533D08AD, DB5Z3504HE</p> <p>INA</p> <p>A00229, A0022905, F565922, H095231142, F56592202, H0952311421, 452001957, 16H0403, F565922, F565922020061, F565922020061CC</p>	Ford Explorer V (2010-2015)

More new products at <https://www.atg-components.com/warehouse-news>