




EPS motor ECU mosfet block Part No. 30180096



Application
Ford Fusion 2012 - , Lincoln MKZ (hyb) (2010-2012), FORD Mondeo V 2014-, Volvo XC90/XC60 2014-

FITS THE FOLLOWING

Rack part number	Crossreferences	Application
ATGE40881RB	<p>FORD</p> <p>HP5C3D080BM, DG9C3D080AH, EG9Z3504A, DG9Z3504BE, HG9C3D080AK, DG9C3D080AK, FG9Z3504B, EG9C3D080AC, DG9Z3504AE, HG9C3D080AJ, DG9C3D080AJ, EG9Z3504AE, DG9Z3504CE, HG9Z3504AE, DG9C3D080AL, FG9Z3504CE</p>	<p>Ford Fusion II (2013-) Lincoln MKZ I (Zephyr) (2009-2012) MKZ II (2012-2016)</p>
ATGE41561RB	<p>Bosch</p> <p>7806994806</p> <p>FORD</p> <p>2120439, 1886026, 1939827, 2014124, 2025780, 2358270, 2265024</p> <p>FORD</p>	<p>Ford Mondeo V (2015-)</p>



	FG9C3D070FA, FG9C3D070CC, HG9C3D070GA, FG9C3D070CE, FG9C3D070CD, FG9C3D070CC, FG9C3D070CB, JG9C3D070BA	
ATGE41571RB	FORD 2174560, 2274332, 2262870, 2322489, 2243184, 2318969, 2322929, KG9C3D070BC, KG9C3D070BB, KG9C3D070BA, JG9C3D070FB, JG9C3D070FA, JG9C3D070BB, JG9C3D070BA FORD 1886028, 2014130, 2025783, 2120436, 2356397, 2265022, FG9C3D070ED, HG9C3D070EA, FG9C3D070EC, FG9C3D070EB, FG9C3D080AB, KG9C3D070HA	Ford Mondeo V (2015-)
ATGE42191RB	Bosch 7818994946, 7838974465, 7838974763, 7838974421, 7828994166, 7838974761, 7838974423 VOLVO 50877450, 31681935, 31387132, 31506187, 36010326, 31658029, 31476413, 36003045, 31451426, 36003166, 31476833, 36010324, 31681508, 32246798, 36012810, 31681510, 36003240, 32315402, 32283810, 36012866	Volvo S90 II (2016-2020) V90 II (2016-2020) V90 Cross Country I (2016- 2020) XC60 II (2017-) XC90 II (2014-2019) XC90 II (2019-)

More new products at <https://www.atg-components.com/warehouse-news>