




Tool for disassembly of plastic pressure piece Part No. TLS20259



Application
Audi A3 III (8V) (2012-2016), Audi A3 III (8V) Restyling (2016-2020), Audi Q2 I (2016-2020), Audi TT III (8S) (2015-), SEAT Ateca (2016-), SEAT Leon III (2013-2016), SEAT Leon III Restyling (2016-2020), Skoda Karoq (2017-), Skoda Octavia III (2013-2017), Skoda Octavia III (2017-2020), Skoda Superb III (2015-), Volkswagen Golf VII (2012-2017), Volkswagen Golf Sportsvan I (2014-2017), Volkswagen Jetta VI (2010-2015)

FITS THE FOLLOWING

Rack part number	Crossreferences	Application
ATGE42541RB	Bosch KS00003326, KS00003124, KS01004237, KS01004037 VAG 5QM423053, 8V1423053D, 3Q1423053, 3Q1423053B, 3Q1423053C, 3Q1423053E, 3Q1423053F, 3Q1423053G, 5Q1423053AC, 5Q1423053AD, 5Q1423053AF, 5Q1423053AG, 5Q1423053AH, 5Q1423053AJ, 5Q1423053AK, 5Q1423053AL, 5Q1423053E, 5Q1423053F, 5Q1423053G, 5Q1423053H, 5Q1423053J, 5Q1423053K, 5Q1423053L, 5Q1423053P, 5Q1423053Q, 5Q1423053R, 5Q1423056,	Audi A3 III (8V) (2012-2016) A3 III (8V) Restyling (2016-2020) Q2 I (2016-2020) TT III (8S) (2015-) SEAT Ateca (2016-) Leon III (2013-2016) Leon III Restyling (2016-2020) Skoda Karoq (2017-) Octavia III (2013-2017) Octavia III (2017-2020) Superb III (2015-)



	<p>5Q1423056A, 5Q1423056C, 5Q1423056D, 5Q1423056E, 5Q1423056F, 5Q1423056G</p> <p>VAG</p> <p>8S1423056, 8S1423053H, 8S1423053J, 8S1423053K, 8S1423053L, 8S1423053M, 8S1423053N, 8V1423053, 8V1423053A</p>	<p>Volkswagen</p> <p>Arteon I (2017-)</p> <p>Golf VII (2012-2017)</p> <p>Golf VII (2017-2020)</p> <p>Golf Sportsvan I (2014-2017)</p> <p>Golf Sportsvan I Restyling (2017-)</p> <p>Passat B8 (2015-)</p> <p>T-Roc I (2017-)</p>
ATGE40691RB	<p>Bosch</p> <p>KS00003277, KS00003676, KS0100440B, KS00001934, KS00002891, KS00003225, KS01001766, KS01004003, KS01004201, KS01004173</p> <p>FAW_VW</p> <p>5QD423051D, 5QD423052A, 5QD423051D, 5QD423051H, 5QD423051R, 5QD423051M, 5QD423051T, 5QD423051AB, 5QD423051AD</p> <p>VAG</p> <p>5Q1423055BC, 5Q1423055BD, 5Q1423055BX, 5Q1423055C, 5Q1423055CX, 5Q1423055D, 5Q1423055E, 5Q1423055EX, 5Q1423055F, 5Q1423055G, 5Q1423055K, 5Q1423055M, 5Q1423055X, 5Q1423051AB, 5Q1423051ABX, 5Q1423051AC, 5Q1423051ACX, 5Q1423051AD, 5Q1423051ADX, 5Q1423051AE, 5Q1423051AEX, 5Q1423051AF, 5Q1423051AFX, 5Q1423051AG, 5Q1423051AGX, 5Q1423051AK, 5Q1423051AKX, 5Q1423051AL, 5Q1423051ALX, 5Q1423051AP, 5Q1423051APX, 5Q1423051AQ, 5Q1423051AQX, 5Q1423051AS, 5Q1423051AT, 5Q1423051BA, 5Q1423051BB, 5Q1423051BC</p>	<p>Audi</p> <p>A3 III (8V) (2012-2016)</p> <p>A3 III (8V) Restyling (2016-2020)</p> <p>TT III (8S) (2015-)</p> <p>SEAT</p> <p>Ateca (2016-)</p> <p>Leon III (2013-2016)</p> <p>Leon III Restyling (2016-2020)</p> <p>Skoda</p> <p>Karoq (2017-)</p> <p>Octavia III (2013-2017)</p> <p>Volkswagen</p> <p>Golf VII (2012-2017)</p> <p>Golf Sportsvan I (2014-2017)</p> <p>Jetta VI (2010-2015)</p>

More new products at <https://www.atg-components.com/warehouse-news>